

# Water Quality Association

## Gold Seal Certificate

### Felker Brothers Corp.

22 North Chestnut Avenue  
Marshfield, WI United States

Facility: Felker Brothers Corp. (Marshfield)

Certification Date: September 27, 2016

Authorized By: Tom Spoden

Tom Spoden  
Director of Product Certification

Water Quality Association  
4151 Naperville Road  
Lisle, IL 60532, USA



ID #0633



Revision: 11/05/2015

FORM.12046

This Certificate, or any part thereof, may not be used in a misleading manner and validation of its use is contingent upon the Official WQA web-listing.

# Water Quality Association Official Gold Seal Listing

Granted to the following company:

Felker Brothers Corp.  
22 North Chestnut Avenue  
Marshfield, WI 42141 United States

For the Facility Located at:

Felker Brothers Corp. (Marshfield)  
1707 East 4th Street  
Marshfield, WI 54449 United States

The WQA Gold Seal Certification Department has issued certification for the following model(s) to the standard(s) below. Only models that appear in the official listing are authorized to bear the WQA Gold Seal.

**NSF/ANSI 61 (03/05/2012): Drinking Water System Components - Health Effects is within WQA's ANSI and SCC approved scope of accreditation under the Drinking Water System Component Scheme**

Stainless Steel Fittings

Stainless Steel Flanges

Stainless Steel Pipe

Stainless Steel Pipe Spools

**NSF/ANSI 372 (07/31/2011) (Previously WQA ORD0902, NSF/ANSI 61, Annex G, California AB 1953) is within WQA's ANSI and SCC approved scope of accreditation under the Drinking Water System Components – Lead Content Scheme**

Stainless Steel Fittings

Stainless Steel Flanges

Stainless Steel Pipe

Stainless Steel Pipe Spools

Notice: To request any changes to the certified model(s), please request a Change to Certified Product (CCP) form. Examples include any change to the wetted parts or formulations such as supplier or material types, literature, or a change in company name. This list is not all inclusive. Failure to submit documentation regarding changes may result in non-compliance with the standard(s) as well as de-listing of the affected models.